

IN THE SPECIFICATION:

Please insert the following two new paragraphs after line 10, page 9 of the specification in the Brief Description of Drawings as follows:

-- Fig. 15 shows a voltage impression method of restoring polarization (time indicated by region B) by superposing polarization recovery voltage Q2 while controlling the position (time indicated by region A) by applying position control voltage Q1 between voltage V1 and V2;

Fig. 16 shows a method of impression of polarization recovery voltage Q2 to the piezoelectric element while increasing continuously from the position control voltage Q1.--